

ASSURING QUALITY OF IMPLEMENTATION UNDER JJM

WEBINAR

ON

11.05.2023

ISHWAR CHAND JAIN
National Wash Expert
Retired Chief Engineer
PHED, Jodhpur

Issues observed during field visit

- 1. FHTC passing through waste water drain;**
- 2. No pedestal support or platform for FHTCs installed in open areas;**
- 2. Leackages in pipe joints & fitting**
- 4. Leakages in overhead tanks/reservoir walls;**

Suggestions

1. During concreting TPI engineer should be present.
2. FHTC connection should be as per approved drawings





